LOAD **MONITORING**







Transmission Dynamics





Rock Breaker, Crusher Copper Mine (July 2021)

Load Monitoring Fastener⁺ installation on rock breaker head



Benefits Reported:

- Enabled an initial assembly that eliminated previously frequent bolt breakage problems
- Eliminated frequent need of unplanned downtime with this equipment due to bolt breakage
- When asked for a testimonial, Rick simply stated, "BADASS"!

Rick Crusher Area Supervisor